

Quality Control



Our quality control procedures are extremely stringent. This company does not sell 'seconds'. We quality check at every step of the production line.

1. Slicing. Our product requires precise measurements, so when we are slicing the materials they are added to a predetermined exact measurement which is then checked manually to ensure compliance. At this stage the quality of the material used is also checked for imperfection. Any imperfection and the material is disposed of. This process is supervised and quality checked by the Floor Manager.
2. Cutting. The projectiles are then cut to size. At this stage of the production it is imperative that the very care is taken to ensure precise cutting with the least amount of wastage. Once again the quality of the material is checked for further imperfections. This process is supervised and quality checked by the Floor Manager.
3. Stripping. This is where the projectiles that have been cut are separated from the wastage material. At this stage any projectiles are disposed of if they are misshapen or have any other imperfection. This process is supervised and quality checked by the Floor Manager.
4. Packaging. Every Projectile is packed by hand to ensure quality control. Once again any projectile that has any imperfection is all disposed of. The packaging is designed to allow no light to enter as this discolours the product. This process is supervised and quality checked by the Floor Manager.
5. Packing. All packing is undertaken to customer requirements and to suit individual freight conditions. This is done to ensure the quality of the product is not compromised in any way. Each order is checked after packing to ensure the order is complete prior to strapping, labelling and wrapping. Each package is clearly labelled and addressed prior to dispatch. This process is supervised and quality checked by the Dispatch Supervisor.

All stages are frequently checked and verified by the General Manager/Managing Director.